

## Cromer Parish Church - Risk Assessment for Cromer Peregrine Project (CPP) - RA 10

HAZARDS/RISKS	EXISTING CONTROLS	LIKELIHOOD	SEVERITY	RISK RATING	ADDITIONAL CONTROLS
Trips or falls on the tower staircase	Monthly maintenance check to ensure there are no hazards and access is clear	1	1	1	
Lighting failure in the tower	CPP members to ensure they have a torch with them (or a torch on a mobile)	1	2	2	
Being locked in	Keyholder to check the tower steps before shutting and locking the door at the foot of the tower. CPP to carry mobile phones when going up the tower	1	2	2	
Accident, injury or sudden illness whilst going up or down the tower steps or on the church roof	CPP members to have thought in advance how to address this	1	2	2	Have a plan for patient be removed from the tower. Ensure two people go up the tower together so there is no lone working.

HAZARDS/RISKS	EXISTING CONTROLS	LIKELIHOOD	SEVERITY	RISK RATING	ADDITIONAL CONTROLS
Fire in the tower	CPP members must all make themselves aware of the evacuation routes from the church, where to muster outside the building and the location of fire appliances. CPP carry mobile phones	1	2	2	
Threatening approach by another person with theft, damage or harm in mind	tower when CPP going	1	2	2	

All CPP members who go up the tower at Cromer Church will be given a copy of this Risk Assessment.

It will be reviewed annually, or more frequently should it be deemed necessary to do so.

DATED: 12/03/21 Reviewed: March 2023 Reviewed: March 2024